

40395 Firenze, Ct
Indio
CA 92203

Date	Estimate #
2/4/2025	94

Name / Address
One Quial Place 72600 Fred Waring Palm Desert Ca 92260

Project

Description	Qty	Rate	Total
Pond Repair Prevailing Wages Water appeared rolling over the parking lot and i dug and it was discovered that the water appears from the bottom of the fountain. To fix this water leak it is necessary to empty the fountain, remove all the gravel that exists and apply a cement with sealant on the affected surface. [If when we discover the entire surface we notice that the cement has to be demolished to repair a PVC pipe under the concrete , this would already be an extra Charge]		6,800.00	6,800.00
Sales TaxSale Tax Item		8.00%	0.00
		Total	\$6,800.00