

Existing clubhouse across parking lot
Spa material finishes to be complimentary.





Existing clubhouse across parking lot - wall stone will be the same



Existing clubhouse across parking lot



Existing clubhouse across parking lot



Existing clubhouse across parking lot



Existing east side of Spa - looking at existing fitness/weight room



Existing building entry



Existing West side - aerobic room, spin room, electrical room



Front facing to the West - New stone curved wall extends into parking space with black SUV in photo.

40' marker

32' marker





Story pole study from main drive entrance to parking lot



Story pole study from main drive entrance to parking lot



Existing parking lot and clubhouse drive under & valet



North East corner



40'

32'

North East corner - Similar perspective to the new rendering.





View from Clubhouse





View from cart parking area



West elevation - over tennis courts.

Clubhouse

Spa

Kiva





40'

32'

Kiva

Existing rear spa roof



Kiva

Tamit place intersection



East existing room equipment area



West roof equipment area



West roof looking at existing to remain spa metal roof areas



Existing interior courtyard - plans show enclosing to become yoga studio and expanded salon space.



Existing interior courtyard - plans show enclosing to become yoga studio and expanded salon space.



Exist tennis courts - no work



Exist landscaping on slope up to Kiva - no work.



Southwest corner of building - repaint only. No work on site or site walls.



South West corner looking north towards clubhouse.





West side facing north



Existing interceptor vault.

West side facing North - new terrace overlooking tennis courts proposed here.



Existing front entry







Existing north facade of fitness/weight room.



East facade of fitness/weight room. outdoor pool to the right.



Existing East facade



Existing pool - no work.



KEEP CLOSED
GATE TO REMAIN CLOSED AT ALL TIMES

Existing pool - no work. South access gate.



South east corner of building and existing to remain retaining walls. No work.



Rear roof at building infill part of atrium enclosing and new treatment rooms 6 & 7



Rear roof at building infill part of atrium enclosing and new treatment rooms 6 & 7
Addition is flush with existing building extents on south facade.



South facade looking to the west.



East facade overlooking the pool from Kiva sidewalk landscaping area.



Pool and spa.

Clubhouse

Main drive lane to parking lot - across intersection from main member gate access into the club.