

Visible Alterations
(08.04.2025)



Figure 1 – Non-original window type in original opening



Figure 2 – Reconfigured driveway and expanded front courtyard



Figure 3 – Front Addition



Figure 4 – Rear Addition



Figure 5 – Non-original windows and door of administrative building set within original building recesses



Figure 6 – Rear second-story terrace addition to clubhouse